Appendix 2: Images of in vivo Study During and After Stress Test



Appendix 2: Images of in vivo Study During and After Stress Test

2) Left Cephalic – Insyte Autoguard I.V. Catheter – Post Stress Test



Study ID 388-01 Date: 07AUG17 Animal ID: 17D119, Left cephalic Insyte Autoguard IV Catheter 3 hr post-Test

Appendix 2: Images of in vivo Study During and After Stress Test



3) Left Jugular- Power PICC Dual Lumen Catheter- During Stress Test

Appendix 2: Images of in vivo Study During and After Stress Test

4) Left Jugular- PowerPICC Dual Lumen Catheter- Post Stress Test



Appendix 2: Images of in vivo Study During and After Stress Test



6) Left Jugular – Arrowgard Coated Polyurethane Catheter – During Stress Test

Appendix 2: Images of in vivo Study During and After Stress Test

7) Left Jugular- Arrowgard Coated Polyurethane Catheter – Post Stress Test

